



Q3 can field wire be connected to any field terminal?

free block with non insulated female spade connectors

factory splice To lock of free block with non insulated female spade connectors