

# Sheet1

	Quantity	Part Number	Manufacturer		Notes
Oil Pan	18	B-10844	AMK		
Oil Pan Ends	6	B-11603	AMK		
Timing Cover	7	B-10844	AMK		
Valve Cover	8	B-10804	AMK		
Fuel Pump	2	B-12723	AMK		1/8" too long (works) but correct washer size (B-11869 is correct but has "TTL" on head)
Water Neck	2	B-11444	AMK		B-12725 is a Chrysler bolt but just a bit too long and bottom out on the original Carter pump
Distributor Clamp	1	B-10804	AMK		
Water Pump Long	2	B-10145	AMK		
Water Pump Short	4	B-10136	AMK		
Water Pump Washers	6	B-11226	AMK		
Fan with 2" Spacer	4	B-12709	AMK		
Alternator Bracket to Block	2	B-13332	AMK		
Alternator Bracket to Block	1	B-13327	AMK		
Alternator Adjustment Bracket to Alternator	1	B-10844	AMK		B-15086 would be nicer with a larger than factory washer
Alternator Adjustment Bracket to Block	1	B-11950	AMK		
Pivot Bolt	1	B-11454	AMK		
Pivot Bolt Nut	1	B-12863	AMK		
Pivot Bolt Washer	1	B-11753	AMK		
Rolled Steel Spacer	1			NA	
Frame to Isolator Nut	2	B-15092	AMK		
Motor Mount Bracket to Isolator Nut	1	B-10519	AMK		
Motor Mount Bracket to Isolator washer	1	B-11363	AMK		
Motor Mount Bracket to Isolator Nuts	2	B-12905	AMK		
Motor Mount to Block	4	B-10184	AMK		
Motor Mount to Block Lock Washer	4	B-13056	AMK		
Bell Housing 1	2	B-13239	AMK		
Bell Housing 2	1	B-10831	AMK		
Bell Housing 3	3	B-10814	AMK		
Bell Housing Cover Bottom	2	B-12300	AMK		
Transmission Brace to Block	2	B-11372	AMK		
Transmission Brace to Transmission	2	B-13329	AMK		
Starter Nut	1	B-10510	AMK		
Starter Stud	1	B-11025	AMK		
Starter Bolt	1	B-13216	AMK		
Starter Bolt/Nut Lock Washer	2	B-13058	AMK		
Flex Plate to Crank	6	B-12701	AMK		Too long, need to be shortened correct not available; 0.66" long should be 0.50"
Flex Plate to Converter	4	B-12687	AMK		0.50" long should be 0.45" but works
Transmission Pan	14	B-10844	AMK		
Manifold Nuts	11	B-12028	AMK		
5/16-24 Reverse Lock Nut (ends)	2			NA	Special..... need to model and have made.
Manifold Studs	13	B-11728	AMK		B-11011 is a little longer than stock and the only specified is a little shorter but worked with Dutras and Offenhauser intake
Conical Washer	1 or 3	B-11476	AMK		Early engines used 3 in the center, later only used one in the middle and batwings
Radiator Bolts (1/4" longer than OEM)	4	B-11895	AMK		
Radiator Support and Sheet Metal	Various	B-11887	AMK		
Radiator Support and Sheet Metal	Various	B-10803	AMK		
Radiator Support and Sheet Metal	Various	B-12047	AMK		
Radiator Support and Sheet Metal	Various	B-12320	AMK		
Radiator Support and Sheet Metal	Various	B-11884	AMK		
					should be correct but not verified on engine
					verified correct on engine
					verified incorrect on engine